


Preliminary Hand- Held Air Monitoring Locations | ITC Deer Park Tank Fire

Reading Date
3/27/2019 2:00:00 PM to 3/27/2019 3:00:00 PM
and Null values



Recent Benzene Detections

Location Category	Reading Date	Concentration
Division A	3/27/2019 14:17:30	0.28 ppm
	3/27/2019 14:16:32	0.35 ppm
Division B	3/27/2019 14:59:40	0.80 ppm
	3/27/2019 14:58:46	0.13 ppm
	3/27/2019 14:38:53	0.15 ppm
	3/27/2019 14:14:19	2.40 ppm
Division E	3/27/2019 14:57:01	7.10 ppm
	3/27/2019 14:55:40	0.05 ppm
	3/27/2019 14:46:53	0.20 ppm
	3/27/2019 14:39:15	4.45 ppm
	3/27/2019 14:39:02	0.19 ppm
	3/27/2019 14:35:13	18.15 ppm
	3/27/2019 14:31:53	16.25 ppm
	3/27/2019 14:26:40	6.89 ppm
	3/27/2019 14:23:11	12.20 ppm
	3/27/2019 14:22:21	19.80 ppm
	3/27/2019 14:09:32	1.71 ppm
	3/27/2019 14:08:23	3.75 ppm
	3/27/2019 14:05:57	1.29 ppm
	3/27/2019 14:03:18	0.25 ppm
	3/27/2019 14:00:35	1.81 ppm
Impacted Tank Farm	3/27/2019 14:31:04	0.66 ppm
	3/27/2019 14:00:46	1.62 ppm
Industrial Area	3/27/2019 14:28:14	0.30 ppm

Not all real time data on this website have undergone full QA/QC (quality assurance/quality control) analysis.
It has been provided expeditiously to regulatory agencies and on-site contractors for informational purposes only